

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION (new)

October 1, 2023

TITLE OF DOCUMENT (new title if applicable):

Copper Standing Seam Roofing, 07 61 16

DATE OF VERSION BEING SUPERSEDED (old):

June 1, 2014

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Copper Standing Seam Roofing, 07 61 16

SUMMARY OF CHANGES IN THIS VERSION:

1. 1.8 APPLICABLE PUBLICATIONS Updated publication dates of referenced industry standards.
2. Minor grammatical changes

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION (new)

June 1, 2014

TITLE OF DOCUMENT (new title if applicable):

Copper Standing Seam Roofing, 07 61 16

DATE OF VERSION BEING SUPERSEDED (old):

April 22, 2010

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Batten Seam Sheet Metal Roofing, 07 61 16

SUMMARY OF CHANGES IN THIS VERSION:

1. Dates of Applicable Publications have been updated to reflect current editions.
2. Section checked and confirmed to comply with Section 508 of the Rehabilitation Act of 1973.
3. Part 1 reference to new Division 1 Section 01 81 11 "Sustainable Design Requirements" added.
4. Added provision for Pre-Installation Conference.
5. Modified the section to specify standing seam copper field-fabricated roofing instead of batten seam roofing.