

# Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.  
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

**DATE OF THIS VERSION (new)**

October 1, 2023

**TITLE OF DOCUMENT (new title if applicable):**

Sectional Doors, 08 36 13

**DATE OF VERSION BEING SUPERSEDED (old):**

June 1, 2014

**DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):**

Sectional Doors, 08 36 13

**SUMMARY OF CHANGES IN THIS VERSION:**

1. 1.6 C. Dates of Applicable Publications have been updated to reflect current editions.

# Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.  
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

**DATE OF THIS VERSION (new)**

June 1, 2014

**TITLE OF DOCUMENT (new title if applicable):**

Sectional Doors, 08 36 13

**DATE OF VERSION BEING SUPERSEDED (old):**

May 1, 2010

**DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):**

Sectional Doors, 08 36 13

**SUMMARY OF CHANGES IN THIS VERSION:**

1. Dates of Applicable Publications have been updated to reflect current editions.
2. Section checked and confirmed to comply with Section 508 of the Rehabilitation Act of 1973.
3. Part 1 reference to new Division 1 Section 01 81 11 "Sustainable Design Requirements" added.
4. Units of measurements reversed to the order of metric followed by English units.
5. Subsection 2.3: Added minimum base metal thickness for door panels.